

509 Harbourfront temporary service change

Gardiner Expressway underpass - City inspection Bathurst Street and Lake Shore Boulevard

Date: February 8, 2017 (starting at 9 p.m.)

*content/timeline accurate at time of printing

Work description and purpose

On the evening of Wednesday, February 8, the City of Toronto will be inspecting the underside of the Gardiner Expressway spanning Bathurst Street north of Lake Shore Boulevard, requiring TTC to shut off power to the streetcar overhead wires. A portion of the 509 Harbourfront streetcar route will be affected by this power shut off – see **TTC service details below**.

City work hours

The City inspection will take place between the hours of 9 p.m. to 5 a.m.

TTC service changes - February 8 (9 p.m. to end of service)

- **509 Harbourfront streetcars** will operate between Union Station and Spadina/Queens Quay Loop.
- **509 Harbourfront shuttle buses** will operate between Spadina/Queens Quay Loop and Exhibition Place (Princes' Gates Loop).
- **511 Bathurst route** is currently operating with buses and will be maintained through the City's inspection area/zone.
- Regular streetcar service resumes on Thursday, February 9.
 - Customers must transfer between 509 Harbourfront streetcars and 509 shuttle buses at Spadina/Queens Quay Loop to continue their trip on the 509 route.
 - Customers can transfer to 510 Spadina streetcars to continue their trip on east to Union Station or north to Spadina Station.



TTC contacts

- Customer Service, 416-393-3030 (daily 7 a.m. to 10 p.m., closed holidays) or @TTCHELPS.
- Paul Tran, Community Liaison, 416-981-1601; paul.tran@ttc.ca.
- Route/Schedules/Fares: 416-393-4636 or ttc.ca.

Upcoming – February 10 to 13

Temporary changes to the 509 Harbourfront and 510/317 Spadina streetcar routes will be required to accommodate a number of maintenance activities inside TTC's Harbourfront tunnel. The City will also be inspecting the Gardiner Expressway spanning Spadina Avenue on February 10. Separate notice to follow.

